



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor 

Mine Name: East Veyo Cinder Knoll
Operator Name: Sunroc Corporation
Dana Truman
180 North 300 East
St. George, Utah 84770

Permit number: S/053/067
Date: September 14, 2006
Time: 12:50 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Active

Weather: Cloudy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site while I was in the area.

Directions to Site:

See previous inspection report.

Inspection Summary:

The area has changed very little since I was here in the spring. The backfilling in the southeastern portion of the excavation is continuing. It appears that the only portion of the site where Sunroc is presently taking materials is in the northwestern portion of the present pit. Pictures of the present operation were taken and are included in this report.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature



Date: 9/29/06

dj:pb

cc: Sunroc Corporation - Dana Truman
Russ Schreiner, BLM, St George FO

O:\M053-Washington\S0530067-EastVeyoCinderKnoll\inspections\0914002006insp.doc

